ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0035, W0037, W0056, W0041, W0054, W0053	NA, Om Shakthi Lyt, 9th Crs	LAKE SIDE AVENUE DEFENCE COLONY
Segment No.	**Total Length (m)**	
13/C-W0035/S035659	214.82	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	26.47	77.517629	13.058846	77.517405	13.058939	W0049	DEAD END
2	16.53	77.516743	13.058662	77.516681	13.058526	W0045	DEAD END
3	104.50	77.516928	13.058640	77.516057	13.059041	W0058	W0056
4	67.32	77.519425	13.059109	77.519091	13.058597	I0042	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS OF CC ROADS AND DRAINS AT LAKE SIDE AVENUE DEFENCE COLONY AND SHANTHI LAYOUT AND OTHER RAODS	4900000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	ROAD AND DRAIN WORK
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	CC ROAD AND DRAIN WORK	013-17-000014
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/61/2016-17	02/09/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9900333496		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		G NAGABHUSHAN
Date of Inspection	**Remarks**	
26/10/2016		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED
AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0035, W0037, W0056, W0041,

Field Inspection Details

Number of Trees	Any Other Information	Name
0		G NAGABHUSHAN
Date of Inspection	**Remarks**	
26/10/2016		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED
AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0035, W0037, W0056, W0041,